



## MANDATORY SERVICE BULLETIN

**SERVICE BULLETIN NUMBER:** 08-18-09-3

**DATE ISSUED:** Aug 18, 2009

**APPLICATION:** Fuel Gasculator

**EFFECTIVE:** Aug 18, 2009

**AIRCRAFT EFFECTED:** All units with Powrachute Gasculators installed.

**BACKGROUND AND INTRODUCTION:**

Due to some blends of fuel and ethanol the plastic bowl will shrink in size and cause the gasculator to leak. In some rare circumstances and fuel blends the bowl will no longer be able to thread into the main housing.

**RECOMMENDATIONS:**

Powrachute, LLC highly recommends that you change the Gasculator Bowl to the new all Aluminum type that is available from the Powrachute factory. To order new style bowl you can call Powrachute @ 574-286-9670

If you have any questions please feel free to contact the factory.

*Powrachute Corp.*  
9425 Spring Creek Ct  
Middleville, MI 49333  
Ph 574-286-9670  
Fax 269-467-9574  
Email [info@powrachute.com](mailto:info@powrachute.com)  
Web [www.powrachute.com](http://www.powrachute.com)