



## SERVICE BULLETIN

**SERVICE BULLETIN NUMBER:** 10-13-08-2

**DATE ISSUED:** Oct 13, 2008

**APPLICATION:** Front Fork Support.

**SERIAL NUMBERS EFFECTED:** A001PEG – A387PEG All units Manufactured before the new Powrachute ownership effective April 1<sup>st</sup> 2005.

**BACKGROUND AND INTRODUCTION:**

Powrachute, LLC. Recently received notification of two separate instances where the Front Fork Support (part# NW-FFS-03-PEG) has broken at the welded portion of the assembly. This was out of our control and all units manufactured after A387PEG have Tig Welded Front Axle Supports.

**RECOMMENDATIONS:**

Powrachute, LLC highly recommends that you change the Front Axle Support to the new style Tig Welded assembly. It seems as though some units in this serial number range have been Mig Welded without proper penetration. You can inspect your Front Fork Support but it will be very difficult to see if any of the welds are cracking from the inside. If you have any questions please feel free to contact the factory at information below.

***Powrachute Corp.***

9425 Spring Creek Ct  
Middleville, MI 49333

Ph 574-286-9670

Fax 269-467-9574

Email [info@powrachute.com](mailto:info@powrachute.com)

Web [www.powrachute.com](http://www.powrachute.com)